


**2022 SCA APPLICATION
PRE-CONSTRUCTION
PHOTOS**

AUGUST 2022

Project Component 1

West 7th Street and Patterson Bridge Road Intersection Repairs



West 7th & Patterson Repairs

Deteriorating road conditions due to inadequate storm drainage



West 7th & Patterson Repairs

Degraded pavement due to large vehicle travel over freeze-thaw conditions




West 7th & Patterson Repairs

Intersection safety risk due to the unmarked road and no curb or sidewalk



Project Component2

East 7th Street and Holmstrom Road Improvements



East 7th Street & Holmstrom Road

Capacity issue for collector street narrowing from two-lane to one-lane



East 7th Street & Holmstrom Road

Degraded road conditions due to lack of stormwater management




East 7th Street & Holmstrom Road

Safety concerns due to unmarked road and no separation of parking area



East 7th Street & Holmstrom Road

Safety concerns from bike/ped conflicts with motorists at local park to be addressed through new curb and landscape barrier



East 7th Street & Holmstrom Road

Intersection closed due to water damage and needed road repairs



East 7th Street & Holmstrom Road

Intersection closed due to water damage and needed road repairs

